

REASON PORSCHE

Unit 16-17 Stone Street, Crowfield, Ipswich, IP6 9SZ
Tel: 01473 845007 Email: service@reasonporsche.com Web: www.reasonporsche.com

<div style="border-top: 1px solid black; border-right: 1px solid black; border-bottom: 1px solid black; padding: 5px;"> <p>WARRANTY FIRST (WARRANTY FIRST) 1 BRAMHALL PLACE STOREYS BAR ROAD PETERBOROUGH CAMBRIDGESHIRE PE1 5YS</p> </div>		<div style="border-top: 1px solid black; border-right: 1px solid black; border-bottom: 1px solid black; padding: 5px;"> <p>Invoice No. 2624</p> <p>Date 20 May 2024</p> <p>Account No. XXXXXXXXXXXXXXXXXXXX</p> <p>Make PORSCHE</p> <p>Model MACAN D S PDK</p> <p>Registration XXXX</p> <p>Mileage 81576</p> </div>
---	--	---

V1DNJ (81576) miles , PORSCHE - MACAN D S PDK

Labour	Net	Net Total	VAT	Total
6.00 Remove left and right front suspension assembly to replace both front coil springs.	£90.00	£540.00	£108.00	£648.00
Total		£540.00	£108.00	£648.00

Parts	Net	Net Total	VAT	Total
1.00 PORSCHE P95B411105AS504 95B MACAN FRONT SPRING PAIR	£168.95	£168.95	£33.79	£202.74
Total		£168.95	£33.79	£202.74

Description	Net	Net Total	VAT	Total
1.00 Geometry laser re-alignment to all wheels/suspension	£165.00	£165.00	£33.00	£198.00
1.00 ADAS Calibration of 2 cameras. Front camera for headlight assist and also Lane departure camera.	£250.00	£250.00	£50.00	£300.00
1.00 Excess and additional items including other spring replacement, Geometry & ADAS required. Paid for by David Jackaman	-£705.00	-£705.00	-£141.00	-£846.00
Total		-£290.00	-£58.00	-£348.00
Invoice Total		£418.95	£83.79	£502.74

Payer Summary	Paid	Outstanding	Net	VAT	Total
XXXXXXXXXXXXXXXXXXXX WARRANTY FIRST (WARRANTY FIRST)	£0.00	£502.74	£418.95	£83.79	£502.74

Bank Details:
Reason Porsche Ltd
Account No: 49857649
Sort Code: 52-30-31