

REASON PORSCHE

Unit 16-17 Stone Street, Crowfield, Ipswich, IP6 9SZ
Tel: 01473 845007 Email: service@reasonporsche.com Web: www.reasonporsche.com

~~MR STUART STEVENS~~
~~BOSCH CONTACT~~
~~MOATS VEX~~
~~COXES XXX~~
~~STOW MARKET~~
~~SHRDLXXX~~
~~XXXXXX~~

Invoice No. 1123
Date 18 March 2022
Account No.
Make PORSCHE
Model 911 CARRERA 4 GTS PDK
Registration S100SOS
Mileage 52943

S100SOS (52943) miles , PORSCHE - 911 CARRERA 4 GTS PDK

Labour		Net	Net Total	VAT	Total
2.00	Intermediate service. Plug in diagnostics and read out fault memory, Replace oil and filter, Replace pollen filter. Inspection of: vehicle underside and engine, coolant hoses, Check antifreeze, Check radiator vents & air intake, Brake system, Drive shafts and CV boots, Suspension and steering joints, Tyre condition and pressures, Lubricate locks and hinges, Electrical equipment, Windscreen wash/wipe system, Power steering and fluid level, Check and lighting system, Check poly ribbed auxiliary belt. Test drive, Re-set service indicator, Wash and vacuum	£80.00	£160.00	£32.00	£192.00
2.50	Remove & replace Tandem Oil Pump and connecting pipe.	£80.00	£200.00	£40.00	£240.00
Total			£360.00	£72.00	£432.00

Parts		Net	Net Total	VAT	Total
7.75	MOBIL 1 521771856 MOBIL 1 FS ENGINE OIL - 0W-40	£12.50	£96.88	£19.38	£116.26
1.00	PORSCHE 0PB115466A/1 997.2 981 OIL FILTER	£15.95	£15.95	£3.19	£19.14
1.00	PORSCHE 333330060 911 987 997 991 SUMP PLUG WASHER	£1.85	£1.85	£0.37	£2.22
1.00	PORSCHE 99757121901/2 POLLEN FILTER 986/996/987/997	£15.95	£15.95	£3.19	£19.14
1.00	PORSCHE P9A111005504 997.2 VACUUM LINE PIPE FOR TANDEM	£76.79	£76.79	£15.36	£92.15
1.00	PORSCHE PA111009006 997 GEN 2 TANDEM OIL PUMP	£136.84	£136.84	£27.37	£164.21
1.00	BOSCH 99662890108/1 986 996 987 997 FRONT WIPER BLADES 582S	£29.95	£29.95	£5.99	£35.94
1.00	PORSCHE P9975753220701C 997 AIR DUCT	£79.49	£79.49	£15.90	£95.39
Total			£453.70	£90.75	£544.45

Description		Net	Net Total	VAT	Total
1.00	Environmental Charge for waste disposal. Top up fluids	£12.50	£12.50	£2.50	£15.00
1.00	Replace brake fluid.	£80.00	£80.00	£16.00	£96.00
1.00	987 997 Remove front bumper and replace condensers, evacuate, re-gas system and check for leaks. replace front bumper	£535.00	£535.00	£107.00	£642.00
1.00	Geometry laser re-alignment to all wheels/suspension	£160.00	£160.00	£32.00	£192.00
Total			£787.50	£157.50	£945.00

Invoice Total **£1,601.20** **£320.25** **£1,921.45**

Payer Summary	Paid	Outstanding	Net	VAT	Total
MR STUART STEVENS	£0.00	£1,921.45	£1,601.20	£320.25	£1,921.45

Bank Details:
Reason Porsche Ltd
Account No: 49857649
Sort Code: 52-30-31